

N49RF ERROR SUMMARY TS Colin HRD KMCFKMCF 06 June 2016



Flight ID: 20160606N1

Sensor or system Number or Name Static Pressure Probe PSM.2 Dynamic Pressure Probe PQM.2 Total Temperature Probe TTM.1 Dewpoint Temp. Probe TDM.1 Vertical Accelerometer AccZfilterI.1 Altimeter AltGPS.3 INE Selection Differential Attack Pressure Probe PDALPHA.1 Differential Sideslip Pressure Probe PDBETA.1 Dynamic Attack Pressure Probe PQALPHA.1 Dynamic Sideslip Pressure Probe POBETA.1 Flight Directory acdata/2016/MET/20160606N1

Local Met Data:

Aircraft Static Pressure (PSM.2)

Tower Pressure (corrected)

Takeoff - 0630Z

1008.4 mb

<u>Landing</u> – 1343Z

1006.0 mb

Notes:

The mission was delayed for about an hour to switch out nose radar systems, from a problem noted on the previous Colin mission.

Takeoff / Landing data: Data before take-off and following landing are potentially suspect.

Calibration problem with PSM.1. PSM.2 performed optimally.

There were no other issues noted in the measured parameters used to calculate meteorological and navigational parameters.

Expendable Type	Number deployed	Number good	Number of messages transmitted
GPS dropwindsonde	17	16	16

Flight Director:

Phone #:

Jack Parrish

(813) 828-4694